


# Structurally Deficient Bridges on the National Highway System

## 3rd Congressional District of Mississippi, 2003



	Structure Number	Road	Location
1	11000550451031B	I 55	0.8 MI N HINDS CL
2	21000490451833B	US 49	4.9 MI N SR 22
3	210008401611120	US 84	0.6 MI E SR 35
4	210008401611140	US 84	0.8 MI E SR 35
5	21000840161258A	US 84	2.9 MI W SR 37
6	21000840161286A	US 84	0.1 MI W SR 37

Structurally Deficient Bridges

Interstate Highways

Mississippi District 3

Cities

US Highways

Urbanized Areas

Airports

State Highways

Park Facilities

Amtrak Routes

Other Rail Lines

Military Bases

Amtrak Stations

Navigable Waterways



U.S. Department of Transportation  
Bureau of Transportation Statistics  
Federal Highway Administration

The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,843 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.